

## EFI Colorproof eXpress Remote Pre-Installation Checklist

- Software and EAC number have been received and are available.
- Validation media has been received and is installed on the printer.
- Color standard has been determined from one of the following industry standards.
  - GRACoL – Commercial sheetfed offset
  - SWOP Grade 3 – Publication web coated
  - SWOP Grade 5 – Publication web uncoated
- Manufacture's print driver installed
  - The printer manufacture's print driver is installed on the system in which EFI Colorproof eXpress will be installed.
  - This driver can be found on the CD provided with the printer or on the printer manufacture's website.
- A test page is printed from within the driver
  - This will verify connectivity to the printer and that it is producing acceptable print quality prior to RIP installation.
- Nozzle check or head cleaning is performed if needed.
  - Test image should print without banding. Color is not critical at this point.
- Verify your system is ready for EFI Colorproof eXpress
  - Operating system
    - Windows XP, Server 2003
    - Mac OS X 10.4, 10.5
  - Hardware
    - Intel Pentium IV
      - 1GB RAM
      - 10/100 MB Ethernet
      - USB port
    - Intel Mac Native, PowerPC G4 or G5
- Initial online tutorial has been viewed
  - <http://www.chromaticity.com/support/remote-install/>
  - Select the **Learning EFI Colorproof eXpress** link
- Computer is WebEx compatible
  - This is required for the remote installation.
  - You can check your system for compatibility at: <http://developers.webex.com/api/jointest/index.php>

Once the checklist has been completed, notify the support team at Chromaticity to begin your installation.

Email: [support@chromaticity.com](mailto:support@chromaticity.com)  
Phone: 616.988.6118

The installation will begin at our WebEx portal. Please connect to the portal prior to the installation at:

<https://chromaticity.webex.com>